Solo 2 DL Release history

Version	Date	Change/additions
02.32.86	Aug, 21st 2020	▪ Signalling of expansions/Wi-Fi: the two upper left shiftlights blink blue ▪ Fix missing data recall graph **External modules** No changes
02.32.78	Jul, 10th 2020	▪ Fixed RPM issue due to wrong RPM factor handling **External modules** No changes
02.32.74	Jun, 15th 2020	▪ Fixed powerup bug that could cause the system to reset (indicated by red LED blinking slowly) **External modules** No changes
02.32.72	Jun, 9th 2020	▪ Japanese language update ▪ Improved timing of RS232/K-line communication (it helps with some ECU protocols) ▪ Added Hour/Date info from GPS tracks ▪ Added reference speed used to calculate odometers **External modules** No changes
02.32.57	Mar, 17th 2020	▪ Minor stability improvements **External modules** No changes
02.32.52	Mar, 9th 2020	NOTE: production-only release ▪ Improved handling of poweroff after fast charge **External modules** No changes

Solo 2 DL Release history

Version	Date	Change/additions
02.32.49	Feb, 13th 2020	NOTE: production-only release
		▪ Improved battery handling
		▪ Solved missing timeout on ECU channels for some serial protocol (RS232 and K-Line)
		External modules
		No changes
02.30.10	Jun, 12th 2019	▪ Fixed bug locking the device in data recall
		▪ AIM CAN network improvements
		External modules
		No changes
02.30.04	May, 2nd 2019	▪ Fixed bug on track auto-learning enabling
		External modules
		No changes
02.30.02	Apr, 19th 2019	▪ Improved K-line protocols management
		▪ Added open tracks management
		▪ Added manual track creation on device
		▪ In data recall added min speed in best lap page and in all laps page
		External modules
		No changes
02.26.55	Mar, 14th 2019	▪ Increased channel frequencies for selected ECUs (in particular K-line- and RS232- based ones)
		External modules
		No changes
02.26.50	Jan, 18th 2019	▪ Performance Race Mode: fix wrong units of measurement in data recall page (MPH and ft were shown but values were in km/h and m)
		▪ ECU: support Adaptronics and Motec M4 ECU drivers
		External modules
		No changes

Solo 2 DL Release history

Version	Date	Change/additions
02.26.38	Dec, 14th 2018	■ Fixed calculated Perfomance Time ■ Fixed "+/- Best Time" display visualization ■ Added "laptime resume visualization" crossing the finish (it can be disabled by menu option) **External modules** No changes
02.26.12	Oct, 30th 2018	■ Support for Can Optical Lap(IRM_42) ■ CAN network fixes ■ 100Hz CAN output management **External modules** No changes
02.26.06	Oct, 5th 2018	■ Fixed bug on backlight set in OFF mode ■ Fixed power off for external modules when Solo 2 DL is in charging mode ■ Fixed bug on Digital output priority handling **External module** ■ **25.47** Lambda
02.24.05	Sep, 21st 2018	■ Custom pages with pressure channels: unit of measure is selectable for each individual channel ■ Performance race: fixed missing performance entry in data recall ■ Fixed bug in led bar handling with predictive lap time **External modules** No changes
02.22.81	Jul, 26th 2018	■ Fixed power consumption in low power mode (board REV00) ■ Fixed multiplexed CAN protocols management **External modules** No changes

AiM Tech Srl - Via Cavalcanti, 8 20063 Cernusco sul Naviglio, Milan - Italy | Tel. +39.02.9290571 | Fax +39.02.92118024

info@aim-sportline.com | www.aim-sportline.com

Solo 2 DL Release history

Version	Date	Change/additions
02.22.67	Jun, 29th 2018	■ Added automatic start data recall at the end of the new test recorded
		■ Fixed bug in Predictive time calculation that in some cases, with high speed applications, caused bad behavior
		■ Fixed bug in System Info menu in "Hw revision" text display
		External modules
		No changes
02.22.65	Jun, 22nd 2018	■ Improved suspend/powerup handling
		■ Support for board revisions C and E
		External modules
		No changes
02.22.58	May, 31st 2018	■ Support of k-line protocols
		External modules
		No changes
02.22.52	May, 18th 2018	■ Added "All Laps" data recall page and "Speed graph with track" data recall page
		■ Added in "Wi-Fi" menu the possibility to choose the Wi-Fi channel to use instead of a random selection at boot
		■ Fixed issue that, sometimes, after a shut down of the system, didn't allow to switch on again the Solo 2 DL
		External modules
		■ **25.47** Lambda